

Lee College Spring Schedule

WELDING	NCCER Modules	Course No	Day	Time (PM)	Start	End	Instructor	Room
Core: <i>Welding Safety, Tools and Equipment</i>	00101 to 00105, 00107 to 00109	WLDG 1323.F001	TTH	6:00 - 7:15	1/17	5/11	Pimentel	W100-C
Welding 1A: <i>Introduction to Welding</i>	29101-15 to 29106-15	WLDG 1200.F01A	MW	6:00 - 7:15	1/17	5/11	Moss	W301-L
Welding 1B: <i>Intro to Shielded Metal Arc Welding</i>	29102-15, 29107-15, 29108-15, 29109-15	WLDG 1428.F01A	MW	7:20 - 9:55	1/17	5/11	TBD	W100-C
Welding 1B: <i>Intro to Shielded Metal Arc Welding</i>	29102-15, 29107-15, 29108-15, 29109-15	WLDG 1428.F02A	TTH	7:20 - 9:55	1/17	5/11	Willets	W100-C
Welding 2A: <i>Intorduction to Blueprint Reading</i>	29201-15, 29202-15	WLDG 1313.F001	TTH	6:00 - 7:15	1/17	5/11	Moss	W201-C
Welding 2B: <i>Advanced SMAW</i>	29111-15, 29112-15	WLDG 2443.F01A	MW	7:20 - 9:55	1/17	5/11	Moss	W101-C
Welding 3B: <i>Introduction to Pipe Welding</i>	46101	WLDG 1435.F01A	MW	7:20 - 9:55	1/17	5/11	Medina	W200-C
Welding 4A: <i>Intro to Metallurgy</i>	29203-15, 29204-15	WLDG 1337.F001	MW	6:00 - 7:15	1/17	5/11	Elliott	W301-C
Welding 4B: <i>Advanced Pipe Welding</i>	29301-16	WLDG 2453.F01A	TTH	7:20 - 9:55	1/17	5/11	Medina	W200-C
Welding 5: <i>Intro to Gas Tungsten Arc Welding</i>	29207-15, 29208-15	WLDG 1434.F01A	TTH	7:20 - 9:55	1/17	5/11	Moss	W201-C
Welding 6: <i>Advanced Gas Tungsten Arc Welding</i>	29304-16, 29305-16	WLDG 2451.F01A	MW	7:20 - 9:55	1/17	5/11	Willets	W201-C
Welding 7A: <i>Intro to Gas Metal Arc Welding</i>	29205-15, 29209-15, 29302-16	WLDG 1430.F01A	TTH	7:20 - 9:55	1/17	5/11	Elliott	W300-C
Welding 7A: <i>Intro to Gas Metal Arc Welding</i>	29205-15, 29209-15, 29302-16	WLDG 1430.F02A	MW	7:20 - 9:55	1/17	5/11	TBD	W300-C
Welding 7B: <i>Intro to Flux Cored Arc Welding</i>	29206-15, 29303-16	WLDG 1312.F01A	MW	5:30 - 7:15	1/17	5/11	Willets	W300-C
Welding 7B: <i>Intro to Flux Cored Arc Welding</i>	29206-15, 29303-16	WLDG 1312.F02A	TTH	5:30 - 7:15	1/17	5/11	Willets	W300-C